



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost		SLAS	<b>COUNTY: Alamance</b> <b>PERMIT NO.: N0431</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** June 6, 2014

**Date of Last Inspection:** November 3, 2011

**FACILITY NAME AND ADDRESS:**

Apple's LCID Landfill  
 Elon-Ossipee Road  
 Elon, NC 27244

**GPS COORDINATES:** N: 36.13920 E: -79.51630

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Ronnie Apple, Operator (property owner's son)  
 h. 336-584-3285  
 c. 336-269-8119

Kitty Apple, Property Owner  
 h. 336-584-6121

**FACILITY CONTACT ADDRESS:**

Ronnie Apple  
 2923 Lowe Road  
 Elon, NC 27244

**PARTICIPANTS**

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)  
 Ronnie Apple, Operator - Apple's LCID Landfill

**STATUS OF PERMIT:**

Land Clearing and Inert Debris Landfill Notification recorded with the Alamance County Register of Deeds September 9, 1998  
 Land Clearing and Inert Debris Landfill Notification approval letter dated January 26, 1999 issued by the SWS  
 Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

**STATUS OF PAST NOTED VIOLATIONS**

None

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

On June 6, 2014, John Patrone met with Ronnie Apple to conduct a comprehensive inspection of the Apple's LCID Landfill on Elon-Ossipee Road in Elon, Alamance County.

1. The land clearing and inert debris landfill (LCID) entrance is located on Elon-Ossipee road, across from mailbox number 1707.
2. The LCID landfill is estimated to be ~ 2 acres.
3. Mr. Apple stated that the LCID landfill is no longer in operation.
4. Per 15A NCAC 13B .0564(9)(b), "The facility shall meet the following buffer requirements: 100 feet from the disposal area to property lines, residential dwellings, commercial or public buildings, and wells."
5. Side slopes should be graded and covered with soil such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
6. Maintain at least one foot of suitable soil cover atop the landfill.
7. Ensure that water does not pool atop the landfill area.
8. Sow grass seed atop bare areas of the landfill cap.
9. Repair erosion rills.
10. The facility is secured by a locked gate.
11. Access roads are of all-weather construction.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 336-771-5095 Fax: 336-771-4631

John Patrone, Environmental Senior Specialist  
Division of Waste Management, NCDENR

Sent on: <u>June 16, 2014</u>		Email		Hand delivery	<b>X</b>	US Mail		Certified No. <u>  </u>
-------------------------------	--	-------	--	---------------	----------	---------	--	-------------------------

Electronic Copies: Jason Watkins, Western District Supervisor - SWS  
Sarah Rice, Compliance Officer – SWS

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Digital pictures taken on June 6, 2014  
by John Patrone DWM-SWS

LCID landfill – view across top



LCID landfill – right top



LCID landfill – side slope (view 1)



LCID landfill – side slope (view 2)

